Approved For Release 2008/03/07: CIA-RDP78B04558A000700110099-5

, 4 (2*

PARTY

P 092107Z

1963 AUG 9 21 42 Z

12 AUG 1963

HFS

CJS

ACT

Grace (File)

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080TH STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBCR/15TH AF, MARCH AFB RIVERSIDE CAL.

RUWGAA/2D RTS BARKSDALE, AFB LA.

DA GRNC

BT

SECRET

CITE CIA-Z-806

15TH AF (FOR DM 4); SAC (FOR DIM, BRASS KNOB DOCR, DM 4). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

- 1. CAMERA B 15 WAS USED IN MISSION 3685 FLOWN ON 7 AUGUST 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS VERY GOOD. THERE ARE 1705 EXPOSURES IN THIS MISSION.
- B. 9R SIDE: THERE ARE 2 CHEMICAL STAINS 10" LONG AND 2" WIDE IN FRAME 93. HEAVY STATIC ASSOCIATED WITH A MANUFACTURER'S SPLICE IS NOTED IN FRAME 201. SEVERAL EMULSION GOUGES ARE NOTED IN FRAME 902. FRAMES 920 THROUGH 1199 CONTAIN OCASSIONAL FINE EMULSION SCRATCHES 4.0" FROM AND PARALLEL TO THE OUTBOARD EDGE.

Declassification Review by NGA/DoD



GROUP 1
Excluded from automatic downgrading and declassification

FRAMES 1227 THROUGH 1255 ARE CREASED THROUGH THE CENTER OF THE FORMAT. THERE IS A 3.0° BAND OF FOG ADJACENT TO A HEAT SPLICE IN FRAME 1346, AND THERE ARE CREASES IN FRAMES 1345, 1346 AND 1347. STARTING AT FRAME 1672 THERE ARE SEVERE CREASES CONTINUING TO FRAME 1782.

- C. 9L SIDE: THERE ARE PLUS DENSITY AREAS ASSOCIATED WITH THE CAMERA PRESSURE ROLLER ALONG THE INBOARD EDGE THROUGHOUT THE MISSION. THERE IS ALSO MINOR OUTBOARD EDGE CRIMPING THROUGHOUT. INBOARD EDGE STATIC IS NOTED INTERMITTENTLY. THERE IS A MANUFACTURER'S SPLICE IN FRAME 167 AND CREASES AND FOG IN FRAMES 165, 166 AND 167. MINOR PLUS DENSITY STREAKS ARE NOTED ALONG THE INBOARD EDGE FROM FRAME 388 TO FRAME 395. A PLUS DENSITY STREAK LOCATED 3.2" FROM THE OUTBOARD EDGE STARTS IN FRAME 793 AND CONTINUES TO THE END OF THE MISSION. THERE IS HEAVY FOG AND A MINOR CREASE ASSOCIATED WITH A HEAT SPLICE IN FRAMES 1217 THROUGH 1221. THERE ARE MULTIPLE FINE PLUS DENSITY LINES THROUGH THE CENTER THIRD OF THE FORMAT STARTING AT FRAME 1353 AND CONTINUING TO THE END OF THE MISSION.
- D. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES WERE NOTED ON THIS MISSION.

3. POSITIVE:

- A. THE PI SUITABILITY IS VERY GOOD. THE PRINTING AND PROCESSING ARE GOOD.
 - B. CLOUDS COVER APPROXIMATELY 10 PERCENT OF THE MISSION.
 END OF MESSAGE